

Date: Thursday, 10/04/2008 1:27:58 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD CROSSTUBE SUPPORT CHANGE

Job Number: 38523

Part Number: DSI9396011

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

DO08104/10

Job Completion



mf 08-04-10.

U

Date: Thursday, 10/04/2008 1:27:58 PM  
 User: Linda Lacelle

## Process Sheet

|                                    |  |                           |                              |
|------------------------------------|--|---------------------------|------------------------------|
| <b>Customer</b> :                  | CU-DAR001 Dart Helicopters Services                              | <b>Drawing Name</b> :     | FWD CROSSTUBE SUPPORT CHANGE |
| <b>Job Number</b> :                | 38523  |                           |                              |
| <b>Estimate Number</b> :           | 13124  |                           |                              |
| <b>P.O. Number</b> :               |  | <b>Part Number</b> :      | DSI9396011                   |
| <b>This Issue</b> :                | 10/04/2008   | <b>S.O. No.</b> :         |                              |
| <b>Prsht Rev.</b> :                | NC   | <b>Drawing Number</b> :   | DSI 9396 REV. B              |
| <b>First Issue</b> :               | //   | <b>Project Number</b> :   | N/A                          |
| <b>Previous Run</b> :              |  | <b>Drawing Revision</b> : | B                            |
|                                    | <b>Type</b> :  | <b>Material</b> :         |                              |
|                                    | SMALL /MED FAB   | <b>Due Date</b> :         | 10/04/2008                   |
| <b>Written By</b> :                |  | <b>Qty:</b>               | 1                            |
| <b>Checked &amp; Approved By</b> : |  | <b>Um:</b>                | Each                         |
| <b>Comment</b> :                   | Est Rev:A 08-01-10 ECN 1075 DD<br>Est Rev:B 08-01-28 ECN 1108 DD |                           |                              |

## Additional Product

Job Number:



| Seq. #: | Machine Or Operation: | Description : |
|---------|-----------------------|---------------|
|---------|-----------------------|---------------|

|     |    |                  |
|-----|----|------------------|
| 1.0 | DC | DOCUMENT CONTROL |
|-----|----|------------------|



Comment: DOCUMENT CONTROL

Photocopy bluefile and create labels as per PPP DSI 9396 CHG001

|     |             |                |
|-----|-------------|----------------|
| 2.0 | D3595063450 | RUBBER CUSHION |
|-----|-------------|----------------|



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

RUBBER CUSHION

batch

35124

50

|     |           |                          |
|-----|-----------|--------------------------|
| 3.0 | MS2192025 | Clamp(per MIL-DTL-8783C) |
|-----|-----------|--------------------------|



Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)

Clamp(per MIL-DTL-8783C)

batch

107236

8/4/10

50 (X)

|     |     |                                    |
|-----|-----|------------------------------------|
| 4.0 | QC4 | INSPECT 100% KITS FOR COMPLETENESS |
|-----|-----|------------------------------------|



Comment: INSPECT KITS 100% FOR COMPLETENESS

8/4/10

(X)

|     |             |                       |
|-----|-------------|-----------------------|
| 5.0 | PACKAGING 1 | PACKAGING RESOURCE #1 |
|-----|-------------|-----------------------|



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP DSI 9396

PPP Rev:

Draft

8/4/10

50

Location:

(X)